

Welders

Wenzlau Part Number	Description	SIN
------------------------	-------------	-----

Portable DC Welders / AC Generators

209158	Welder, 135 Amp, 1.5kW, 120VAC Gen., 5.5hp Honda GX200, Recoil Start	412 99
209159	Welder, 180 Amp DC, 4 kW/120 VAC Gen., 11hp	412 99
207579	Welder, 250 Amp, 7.2kW, 120/240V Gen., 18hp	412 99
207580	Welder, 225 Amp, 6kW, 120/240V Gen., 12.5hp	412 99
207581	Welder, 300 Amp, 10.5kW, 120/240V Gen., 19hp	412 99
207582	Welder, 400 or (2) 200 Amp, 14kW,120/240V Gen., 31hp	412 99
209160	Welder, 500 Amp, 3kW, 120 VAC, 34hp Kubota Diesel	412 99

Welding Accessories

207585	Remote Control Cable and Rheostat (2 required for BLW400SS)	412 99
207586	Cable, 50 ft., #2, with Electrode Holder	412 99
207587	Cable, 100 ft., #2, with Electrode Holder	412 99
207588	Cable, 150 ft., #2, with Electrode Holder	412 99
207589	Cable, 50 ft., #1/0, with Electrode Holder	412 99
207590	Cable, 100 ft., #1/0, with Electrode Holder	412 99
207591	Cable, 150 ft., #1/0, with Electrode Holder	412 99
207592	Cable, 50 ft., #2, with Ground Clamp	412 99
207593	Cable, 100 ft., #2, with Ground Clamp	412 99
207594	Cable, 150 ft., #2, with Ground Clamp	412 99
207595	Cable, 50 ft., #1/0, with Ground Clamp	412 99
207596	Cable, 100 ft., #1/0, with Ground Clamp	412 99
207597	Cable, 150 ft., #1/0, with Ground Clamp	412 99

Notes

1. GSA Federal Supply Schedule contract number: GS-07F-0283M.
2. Freight is F.O.B. origin.